

STATE OF FLORIDA  
DEPARTMENT OF HEALTH  
COUNTY HEALTH DEPARTMENT  
PUBLIC SCHOOL  
INSPECTION REPORT



1 of 2

**Facility Information**

**RESULT: Satisfactory**

Permit Number: 13-51-1367749  
 Name of Facility: Bowman Ashe/Doolin K-8 Academy #2 Mid  
 Address: 6601 SW 152 Avenue  
 City, Zip: Miami 33193  
  
 Type: Public Schools  
 Owner: Miami-Dade County School Board  
 Person In Charge: Lisset Vazquez Phone: (305) 386-6656  
 PIC Email: lissetvazquez@dadeschols.net

**Correct By: Next Inspection**  
**Re-Inspection Date: None**

**Inspection Information**

Purpose: Routine  
 Inspection Date: 7/8/2020

Begin Time: 08:55 AM  
 End Time: 09:50 AM

**Additional Information**

FEMALES ..... CENSUS ..... 0  
 MALES .....

*This form serves as a "Notice of Non-Compliance" pursuant to section 120.695, Florida Statutes. Items marked below violate one or more of the requirements of Rule 6A-2.0010, of the Florida Administrative Code, Chapter 5, section 5 of the State Requirements for Educational Facilities 2014 (SREF); and sections 453 and 468 of the Florida Building Code 6th Edition (2017). Violations must be corrected within the time period indicated above. Continued operation of this facility without making these corrections is a violation. Failure to correct violations in the time frame specified may result in enforcement action being initiated by the Department of Health.*

**Violation Markings**

SCHOOL SANITATION	<b>IN</b> 11. Group Toilet Rooms	<b>IN</b> 21. Pest Control
<b>IN</b> 1. School Site	<b>IN</b> 12. Toilet Facilities	SAFETY
<b>IN</b> 2. Playground, Equip & Athletic Fields*	<b>IN</b> 13. Handwashing Facilities	<b>IN</b> 22. First Aid Kit
<b>IN</b> 3. Athletic & Playground Equipment	<b>IN</b> 14. Soap Dispensers	DIAPER CHANGING STATION
BUILDING CONST/MAINT.	<b>IN</b> 15. Shower Facilities	<b>NA</b> 23. Sanitizers
<b>IN</b> 4. Construction	<b>IN</b> 16. Showers Water Temperatures	<b>NA</b> 24. Changing Station & Mats
<b>OUT</b> 5. Maintenance & Repair	WATER SUPPLY	<b>NA</b> 25. Hand Sink
<b>IN</b> 6. Lighting Standards	<b>IN</b> 17. Approved Source	<b>NA</b> 26. Garbage Can
<b>IN</b> 7. Heating, Ventilation, A/C Standards	<b>IN</b> 18. Drinking Fountains	ANIMAL HEALTH & SAFETY
<b>IN</b> 8. Natural Ventilation	LIQUID WASTE & WASTE WATER	<b>NA</b> 27. Animal Maintenance/Aggressive
<b>IN</b> 9. Mechanical Ventilation	<b>IN</b> 19. Sewage Disposal	DORM/RESIDENTIAL FACILITIES
SANITARY FACILITIES	<b>IN</b> 20. Solid Waste	<b>NA</b> 28. Maintenance/Complaint
<b>IN</b> 10. Provided/Accessible/Separation	PEST CONTROL	<b>NA</b> 29. Other

Marking Key: **IN** = the act or item was observed to meet standards; **OUT** = the act or item was observed not to meet standards; **NO** = the act or item was not observed to be occurring at the time of inspection; **NA** = the act or item is not performed by the facility or not part of the operation

Violation Key: \* = 2. Playground, Equipment & Athletic Fields

Inspector Signature:

Client Signature:

*Emailed to Client*

STATE OF FLORIDA  
DEPARTMENT OF HEALTH  
COUNTY HEALTH DEPARTMENT  
PUBLIC SCHOOL  
INSPECTION REPORT



2 of 2

### General Comments

Satisfactory

-Inspection conducted during the COVID-19.

-No current census available due to closer for the summer. Custodial staff were on site at time of inspection.

Email Address(es): lissetvazquez@dadeschols.net;  
jaybolton@dadeschools.net;  
jware@dadeschools.net;  
ipalacios@dadeschools.net

### Violations Comments

Violation #5. Maintenance & Repair

-Adjust loose faucet in the girl restroom 132.

-Replace light bulbs in classroom 603, 723, 803, and 805.

-Repair faucet in the girl restroom 807.

-Repair apparent water damage on the North wall of 805 classroom. Biological growth was observed. The base board located below the writing board was detached and painting was coming off.

CODE REFERENCE: 5. Maintenance and Repair. 5(1)(e)8.h SREF. Light fixtures and window surfaces, both inside and outside, shall be kept clean, serviceable, and in good repair at all times. 5(1)(e)8.i. Custodial areas shall be kept clean, safe, and orderly at all times. Custodial equipment shall be in good repair at all times. 5(1)(e)8.j SREF. Building components & finishes shall be kept clean & in good repair.

Inspection Conducted By: Lucia Gonzalez Melendez (913031)  
Inspector Contact Number: Work: (305) 623-3500  
Print Client Name: Bowman Ashe/Doolin K-8 Academy #2 Mid  
Date: 7/8/2020

Inspector Signature:

Handwritten signature of Lucia Gonzalez Melendez.

Client Signature:

Handwritten signature "Emailed to Client".